

RECORD OF  
COMMUNICATION

☒ Phone Call ☐ Discussion ☐ Field Trip  
☐ Conference ☐ Other (Specify)

(Record of Item Checked Above)

TO: Dick Moncure  
Environmental Coordinator  
Gary Job Corp. Center

FROM: Brenda Nixon Cook  
FIT Chemist

DATE  
10-21-87  
TIME  
1500

SUBJECT

Status of PCB transformers & possible location of past landfills.

SUMMARY OF COMMUNICATION

Mr. Moncure confirmed the date that the transformer pole broke was 9-17-87 and that the building number for the transformer storage facility was 9-356. He stated that the city at one time had a municipal landfill east of the airstrip. When asked about previous military landfills, he stated that he thought there had been 2 fuel dumps, one at the east and one at the west end of the airport ramp, and 2 or 3 landfills northeast of the airstrip. When questioned about the probable location of the buried tetraethyl lead, he said he did not know for sure but his guess would be near the fuel dumps.

CONCLUSIONS, ACTION TAKEN OR REQUIRED

INFORMATION COPIES

TO: